

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

1/12

3700
1-12



(PRIOR ART)
 Fig. 1a

2065020-59/292001

165
81

(PRIOR ART)
Fig. 1c

Fig. 1d

(PRIOR ART)

**HOT
EXHAUST
GAS**

100

Fig. 2

HEATED AIR

TURBINE

OL AIR

**COOLED
EXHAUST
GAS**

4/12




Fig. 3

205020-52/2000

5/12




Fig. 4

6/12




FIG 5a

7/12




Fig. 5b




Fig. 5c




Fig. 5d




Fig. 5e

10068765.020506

8/12




Fig. 6




Fig. 7

10066765-020502

9/12





Fig 7a

10063763-000502

10/12



40066765-000000

11/12





Fig. 9b




Fig. 9c

Fig. 9a

40066755-000000

12/12




Fig. 10

2006/05/23 10:05:00